

1998 Bombardier Learjet - 31A

S/N: 160

N160CF

HIGHLIGHTS

— MSP Gold

New 2015 Interior Refurb!

Dee Howard T/R's

Raisbeck Aft. Storage Locker

— Cargo Door

Single Point Refueling

EROS Oxygen Masks

— DeVore Tail Logo

AIRTIME

4185 TTAF

3853 Landings

Questions? Contact:

Sales Team info@MeisnerAircraft.com 262,763,6600







ENGINES *ON MSP GOLD

Honeywell TFE731-2-3B with FRESH 0/0 ZERO TIME CZI's



Left Engine

Total Time: 4,040 hrs

Total Cycles: 2,995



Right Engine

Total Time: 3,310 hrs

Total Cycles: 2,804

MAINTENANCE

A Checks Due: June 2015

B Checks Due: November 2016

C Checks Due: November 2016

D Checks Due: May 2021

12 Year Inspection Due: July 2021

Both Engines FRESHLY overhauled by Honeywell (R&R by Duncan). 0/0 Time as of Feb 2015

AVIONICS

Dual King ADF-43's

Bendix/King KFC-3100 Autopilot

Collins 5 Tube EFIS Proline II

CVR/FDR

Universal UNS-1C w/GPS

Dual King VNS-41's w/FM Immunity

Honeywell Mark VII EGPWS

Dual King MST-67A Mode S Enhanced

Dual Collins VHF-22C's w/8.33 Spacing

Dual King DM-441B DME

King KHF-950

Dual King KRA-405 Radar Alteimeters

TCAS-II w/Change 7

King RDR-2000 Radar

Questions? Contact:

Sales Team info@MeisnerAircraft.com 262.763.6600







INTERIOR

NEW Refurbished February 2015: Warm beige & taupe interior leather seating for 8 includes 4-place club, aft 3-place bench seat and belted lav seat. Forward LS refreshment center. Cabinetry is high-gloss medium tone straight grain veneer woodwork that includes B&D cabin display. Excellent condition!

EXTERIOR

NEW in 2008: Overall Matterhorn White with Titanium Silver and Royal Blue Striping. Excellent condition!



Questions? Contact:

Sales Team info@MeisnerAircraft.com 262.763.6600















Questions? Contact:

Sales Team info@MeisnerAircraft.com 262.763.6600



